

STATUS: Finished / In-Progress

GameCube Mods and Repair

modding and repair of GameCube systems.



Items Needed

- Xeno-ModChip
- Laser assembly

Instructions

- Step 1
- Step 2

NOTES

Laser Eye Assembly always needs tweaked. **LOWER Ohms = MORE LASER**

Start with higher resistance and work your way down slowly.

200 to 500 Ohms is the average resistance. **DO NOT GO UNDER 175!!!**

001 GC laser needs resistance set between 450 - 600 101 GC laser needs resistance set between 150 - 250

More Information

A youtube or [🌐 URL](#) etc

Last update: 2023/10/06
23:20

projects:gamecube <https://home.woodchuckhunters.com/wiki/doku.php?id=projects:gamecube&rev=1696634424>

From:
<https://home.woodchuckhunters.com/wiki/> - **DavWiki1**

Permanent link:
<https://home.woodchuckhunters.com/wiki/doku.php?id=projects:gamecube&rev=1696634424>

Last update: **2023/10/06 23:20**

